

The purpose of this form is to provide SLAC with a brief summary of deviations from drawings or specifications for each undulator assembly being delivered by ANL.

Undulator Assembly No. 1

Name of Assembly Organization: Hi-Tech Manufacturing Inc.

ANL PO#: 5A-13624

No.	Deviation	Reported by	Reporting method	Disposition	Disposition by
1	Drill broke during process, remains stuck in hole. Hole is oversize as a result of removal attempts	Dial Machine, S. Lewis	Supplier Disposition Request #1	Plug and re drill.	G. Lawrence
2	Machine tool made false start, cutting support flat approx 1" wide, 1/4" deep.		Supplier Disposition Request #2	Accept as is, will not have an effect on Strongback function.	G. Lawrence
3	<p>The supplier has not provided certification that the forgings have been inspected or tested in accordance with ASTM B381 Grade F2 as required by section 4.1.1 of the SOW.</p> <p>The supplier has not provided certification that the forgings were annealed according to AMS-H-81200A or provided copies of the temperature profiles as required by section 4.1.2.2 of the SOW.</p> <p>The heat number on the mill certificate provided by the supplier is not clear because the language on the mill certificate is Russian.</p>		ANL Report of Nonconformance #473	<p>Accept as is. Supplier unable to provide certification or reconcile in accordance with the SOW. The SOW calls for a forging made from, the Dial's material was forged from a bar material and should have no effect.</p> <p>Accept as is.</p> <p>Accept as is. T. Barsz reviewed the mill certificate with E. Trakhtenberg and found it to be acceptable.</p>	G. Lawrence
4	<p>The supplier is unable to provide copies of part temperature profiles required by section 4.2.1.3 of the SOW. The test report provided shows a temperature 1250 degrees and a soak time of 4 hours.</p> <p>The supplier reported the 1.6 Surface Roughness ranged from 1.3 to 2.8. The supplier attributed the result to the type of milling cutter used to machine the 167.00 dimension.</p> <p>The supplier did not inspect the 15.0 diameter counterbored holes in accordance with ANSI Y15.4 section 3.4.3. The supplier used Datum B as the primary datum instead of Datum A.</p> <p>The Go/NoGo thread gages used by the</p>		ANL Report of Nonconformance #474	<p>Accept for first article only since surface B perpendicularity was reported as .004mm. Supplier to modify its inspection procedure to make datum A the primary datum for the remaining Strongbacks.</p> <p>Accept as is for first article only. Supplier to have the thread gages calibrated for the remaining Strongbacks.</p> <p>Accept as is. Supplier to make a 2" wide hard gage to verify the 167.00 dimension on the remaining Strongbacks after verifying the accuracy of the hard gage with calibrated gage blocks.</p> <p>Accept as is. Supplier to improve its cleaning process and add a requirement</p>	G. Lawrence

<p>supplier to accept the tapped holes were out of calibration. Some of the thread gages did not have any calibration labels.</p> <p>The gage blocks used to verify the 167.00 dimension were not calibrated since 6/8/04. The gage blocks could not wrung together indicating that the gage blocks are very worn.</p> <p>The threaded holes contained machining debris and did not to be adequately cleaned.</p>			<p>for checking cleanliness on its inspecton sheet.</p>	
---	--	--	---	--